

1. Broken or damaged cable jacket

2. Wrap damaged area with insulating tape, wrap multi-layer on the broken cable surfaces

3. Wrap fiberglass mesh tape multi-layer on the tape surface

Brush with DC6150

